



60100B1-1  
INDICATOR, UNIVERSAL  
CDI .001/.20  
ASSEMBLY

K02-0015  
INSERT, FOAM  
BOTTOM PAD  
GROUP 1  
PART OF K02-0013

K02-0017  
INSERT, PRIMARY  
PAD GROUP1  
PART OF K02-0013

K02-0016  
INSERT, FOAM  
TOP CONVOLUTE  
PART OF K02-0013




K01-0024  
BOX, MECHANICAL  
SET SMALL CDI

CDI5337  
POINT, 3/8  
BUTTON  
SEE NOTE 1



CDI524062  
POINT, 13/32"  
TAPERED  
SEE NOTE 1



NOTE:  
1. PLACE CDI5337 & CDI524062 IN  
A ZIPPER TYPE PLASTIC BAG AND  
LAY IN BOX.

60100B1