

**PARTS BREAKDOWN** 

372 Old US Highway 52 South Mount Airy, NC 27030 Model:

8050


**Product Type:** 

ADJUSTABLE DARKENING FILTER
WELDING HELMET - VARIABLE DIN 9-13

Call 1.800.221.9705 for questions concerning performance of the product or other inquiries.

## **Parts List**

Index No.	Part No.	Description							
1	8050-01	Shade Knob	1						
2	8050-02	Block Nut	2						
3	8050-03	Auto Darkening Filter Cartridge	1						
4	8050-04	Front Cover Lens	1						
5	8050-05	Block Nut	2						
6	8050-06	Washer	2						
7	8050-07	Shell	1						
8	8050-08	Screw	2						
9	8050-09	adjustable Limitation Washer	1						
10	8050-10	Adjustable Headband	1						
11	8050-11	Limitation Washer	1						
12	8050-12	Two AAA Alkaline Batteries Box	1						
13	8050-13	Fonr Headband	1						
14	8050-14	Sweatband	1						
15	8050-15	Inside Cover Lens	1						



## **SHADE GUIDE TABLE**

	Arc Current (Amperes)																							
Welding Process	0.5		2.5		10		20		40		80	350	125	THE T	175		225	5	275		350		450	
reduing Freecas		1		5		15		30		60		100		150		200	0 25		100	300	reput	400		500
								1				de	7			Sele	1					4	1	110
SMAW				30				9		10		10,8	11			1599	Ball)	12	ns 5	(8)	DISCO	13	(i) (ii)	14
MIG (heavy)			No. of			20	9	THE P		THE R	1	0	1	1	PH P	图心	U FOL	12	(Fig.)	B 199	ie typi	13	(H)	14
MIG (light)		100						RE.			1	0	1	1		1	12	90	THE	13		14		1
TIG,GTAW					9	)		10		1	1		1	12			1	3	77			14		
MAG/CO <sub>2</sub>					Service Services		hos			10	400	11	9 6	12	312			13	division in	3 B	and	4	- 12	15
SAW														10		11	80.0	12	6 1 36	13	10 2	14	1	15
PAC	1							189			3 - Vi	11	156			12				er d	13		N.	
PAW	10000			1	8	9	10	6 3	11	30	1	2	<b>S</b> 8	SH	13	3			100	14		Kila	100	15

2

SMAW - Shielded Metal Arc Welding MIG (Heavy) - MIG on Heavy Metals

TIG,GTAW - Gas Tungsten Arc Welding PAW - Plasma Arc Welding SAW - Shielded Semi-Automatic Arc Welding MIG (Light) - MIG on Light Alloys PAC - Plasma Arc Cutting

7